

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave.St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:**Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-004954**Date Inspected:** 06-Dec-2008**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1700**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Wen Pang**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG**Summary of Items Observed:**

On this date, Caltrans Office of Structure Materials (OSM) Quality Assurance Inspector (QA) Raymond Lara was present at jobsite in Zhenhua Port Machinery Company facility on Changxing island, China for the purpose of observing and monitoring the fabrication of the SAS Superstructure.

Bay 8

The Quality Assurance Inspector performed 10% random ultrasonic testing verification on floor beam assemblies. The Quality Assurance Inspector performed the testing on the following welds; FB0005-038-2,20, FB005-037-2, 20, FB005-036-2,20, FB014-037-2,20, FB014-38-2,20, FB014-039-2, FB014-040-2,20, FB013037-2,20, FB004-039-2,20, and FB004-037-2,20. See Caltrans report TL-6027 Ultrasonic Testing Report, dated Dec. 6, 2008 for additional information.

Summary of Conversations:

No relevant conversations on this date.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Peter Dautermann 150 0219 9593, who represents the Office of Structural Materials for your project.

Inspected By: Lara,Raymond

Quality Assurance Inspector

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

Reviewed By: Wright,Mark

QA Reviewer